


STEP 01


Interconnect aluminum profiles with built-in LED light stripes, connect adjacent LED light stripes with LED connectors.





Insert aluminum profiles without built-in LED light stripes onto feet.







STEPS


STEP 03

Interconnect aluminum profiles by pulling up buckle to insert into & pressing down to lock.



STEP 04


Insert support rods onto aluminum profiles with aligning their holes, interconnect upper & lower parts at sides.



STEPS

STEP 05

Interconnect support rods all around based on cross connectors & insert them onto aluminum profiles with aligning their holes.



STEP 06

Interconnect aluminum profiles by pulling up buckle to insert into & pressing down to lock, align support rods to their holes.









STEPS

STEP 07

Connect LED light stripes with jump wires out to switching power supplies either from left and/or right sides as needed.





STEP 08

Insert silicone edge graphic pieces into channels from corners. (Same Steps for Double Sides)

