



, CO








Press Knobs to




STEP 04

Connect long poles with corner poles according to labelings, connect support poles onto column frame.




STEP 05

Install LED light bars & connect power wires.





① Slide clips from LED light bars to align at holes of poles & press into.





② Connect 2 adjacent LED light bars in series with DC connection wire.





3 Connect those 2 adjacent LED light bars connected with Y-shaped connection wire, slightly adjust space between each LED light bar from 1" to 4".






STEP 06 Wrap column frame with fabric banner & zip up at corner.




STEP 07

Connect Y-shaped connection wire's XT60 connector to switching power supply.








(2) Printed Graphic Fabric Banner (Optional)





STEP 01 Connect to make long poles according to labelings.




STEP 02

Connect long poles with corner poles according to labelings, connect support poles onto frame.













10X10FT-BOOTH-29

(1) Durable Plastic Hard Case, Aluminum Support Poles



(2) Printed Graphic Fabric Banner



STEP 01

Put hard case's top into fabric banner.






STEP 02

Insert support poles into hard case's top & bottom.







STEP 04

Wrap fabric banner from bottom to top & twist it to be smooth, lay hard case's intermediate panel on podium's top.



